


OPTIONAL: use smaller holes and tap instead of welding nuts...maybe good



DIMENSIONS ARE IN INCHES TOLERANCES: FRACTIONAL ± ANGULAR: MACH ± BEND ± TWO PLACE DECIMAL ± THREE PLACE DECIMAL ±		FINISH:		DEBUR AND BREAK SHARP EDGES		DO NOT SCALE DRAWING		REVISION	
						Open Source Ecology			
DRAWN		SIGNATURE		DATE		TITLE: SMOKE YOU SMOKE YOU --			
CHK'D									
APPV'D									
MFG									
Q.A				MATERIAL:		DWG NO		A4	
						Hopper Interface Saddle Weldme			
				WEIGHT:		SCALE:1:10		SHEET 1 OF 1	